



180889\_1.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, 3-D-view 1

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889
 page 1 of 10





180889\_2.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, 3-D-view 2

Examiner: Thomas KÜHN Date of issue: 08/24/2018 Report Number: F180889E4 Order Number: 18-110889 page 2 of 10





180889\_3.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, type plate view

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889
 page 3 of 10





180889\_14.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, 3-D-view 1

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889
 page 4 of 10





180889\_15.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, 3-D-view 2

Examiner: Thomas KÜHN Date of issue: 08/24/2018 Report Number: F180889E4 Order Number: 18-110889 page 5 of 10





180889\_16.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776, type plate view

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889
 page 6 of 10





180889\_11.jpg: MGB2-H-BA1A3-R-136691, 3-D-view

Report Number: F180889E4 Order Number: 18-110889





180889\_12.jpg: MGB2-H-BA1A3-R-136691, type plate view

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 8 of 10
 page 8 of 10





180889\_25.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392 with MGB2-H-BA1A3-R-136691

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 9 of 10
 page 9 of 10





180889\_17.jpg: MGB2-L1-MLI-U-Y0000-BJ-136776 with MGB2-H-BA1A3-R-136691

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E4

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

Page 10 of 10