


Date: 2018-12-11

Report Number: 60.792.18.014.02

Model No.: HG04126A-US






Page 1 of 5 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong




Date: 2018-12-11

Report Number: 60.792.18.014.02

Model No.: HG04126A-US









Date: 2018-12-11

Report Number: 60.792.18.014.02

Model No.: HG04126A-US

Antenna Location:








Date: 2018-12-11

Report Number: 60.792.18.014.02

Model No.: HG04126A-US






Page 4 of 5 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong




Date: 2018-12-11

Report Number: 60.792.18.014.02

Model No.: HG04126A-US





Page 5 of 5 TÜV SÜD Hong Kong Ltd.