

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F16

Report No.



Mode 1




SIDE VIEW

 SPORTON INTERNATIONAL INC.
 Page No.
 : F2 of F16

 TEL: 886-3-327-3456
 Report No.
 : 622623

FAX: 886-3-327-0973









FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F3 of F16

Report No.



Mode 2



SIDE VIEW

 SPORTON INTERNATIONAL INC.
 Page No.
 : F4 of F16

 TEL: 886-3-327-3456
 Report No.
 : 622623

FAX: 886-3-327-0973









FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F5 of F16

Report No.



Mode 3



SIDE VIEW

 SPORTON INTERNATIONAL INC.
 Page No.
 : F6 of F16

 TEL: 886-3-327-3456
 Report No.
 : 622623

FAX: 886-3-327-0973




Appendix F

1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F7 of F16

Report No.




For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F8 of F16

Report No.




Appendix F FCC Test Report





EUT take a close-up



EUT take a close-up


SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973


: F9 of F16 Page No.

Report No.









FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F10 of F16

Report No.









EUT take a close-up



EUT take a close-up


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


: F11 of F16

Report No.










FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F12 of F16

Report No.



Appendix F FCC Test Report





EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No.


: F13 of F16

Report No.



For radiated emissions above 1GHz

Mode 1



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F14 of F16 Report No. : 622623










FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


: F15 of F16

Report No.









FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F16 of F16

Report No.