
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 5



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AJAYJP-LEN Page Number : A1 of A3
Report Issued Date : Aug. 18, 2016
Report Version : Rev. 01

Report No. : FC671404


Report Template No.: BU5-FC15B Version 1.3

CC Test Report No.: FC671404


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AJAYJP-LEN Page Number : A2 of A3
Report Issued Date : Aug. 18, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Test Report No.: FC671404

Mode 5

LF







SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AJAYJP-LEN Page Number : A3 of A3
Report Issued Date : Aug. 18, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3