Test report No. : 11384033H
Page : 34 of 36
Issued date : August 24, 2016
FCC ID : 2AJCWPXPML1

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11384033H
Page : 35 of 36
Issued date : August 24, 2016
FCC ID : 2AJCWPXPML1

Radiated Spurious Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11384033H


 Page
 : 36 of 36


 Issued date
 : August 24, 2016


 FCC ID
 : 2AJCWPXPML1

Worst Case Position

(Below 1GHz: Horizontal: X-axis/ Vertical: X-axis) (Above 1GHz: Horizontal: X-axis/ Vertical: Z-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124