



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 1





Front view




Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A11 Report Version : Rev. 01







Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A11
TEL: 886-3-327-3456 Report Version : Rev. 01





Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A11

Report Version

: Rev. 01







Side view

SPORTON INTERNATIONAL INC. Page No. : A4 of A11
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report Report No.: FR671803-01

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 10.375 MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A11

: Rev. 01

Report Version




FCC Test Report


Report No. : FR671803-01

For radiated emissions 9kHz~30MHz

Mode 1



Front view




Rear view

SPORTON INTERNATIONAL INC. Page No. : A6 of A11 TEL: 886-3-327-3456 Report Version : Rev. 01






Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A11


Report Version

: Rev. 01






Mode 3



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A8 of A11
Report Version : Rev. 01



FCC Test Report


Report No.: FR671803-01

: A9 of A11

: Rev. 01

For radiated emissions 30MHz~1GHz

Mode 1



Front view




Rear view

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version






Mode 2



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A10 of A11 Report Version : Rev. 01





Mode 3



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A11 of A11

Report Version

: Rev. 01