Test report No.
 : 11217143H-A

 Page
 : 18 of 20

 Issued date
 : October 24, 2016

 FCC ID
 : 2AJMDK7001TX

APPENDIX 3: Photographs of test setup

Radiated emission



Photo 1



Photo 2


UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11217143H-A : 19 of 20 Page : October 24, 2016 : 2AJMDK7001TX Issued date FCC ID

Radiated emission Above 1GHz






Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8999 Telephone Facsimile : +81 596 24 8124

Test report No. : 11217143H-A
Page : 20 of 20
Issued date : October 24, 2016
FCC ID : 2AJMDK7001TX

Worst case position

(Below 1GHz Horizontal: X-axis / Vertical: Y-axis) (Above 1GHz Horizontal: X-axis / Vertical: Y-axis)





Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124