

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A Page Number : D1 of D3
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report No.: FR6N0822C

Report Template No.: BU5-FR15CWL AC MA Version 1.3







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A Page Number : D2 of D3
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL AC MA Version 1.3




Report No.: FR6N0822C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A Page Number : D3 of D3
Report Issued Date : Jan. 06, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 1.3