
Appendix C. Setup Photographs

<Radiated Emission>

Y Plane for LTE Band 5

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C1 of C5
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No.: FG790812B

Y Plane for LTE Band 4/26/41/2(for Sample 2)

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C2 of C5
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG790812B

X Plane for LTE Band 7/12

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C3 of C5
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6


Report No. : FG790812B

Z Plane for LTE Band 13(for Sample 2)

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C4 of C5
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No.: FG790812B

LTE Band 2/13/25

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C5 of C5
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.6

Report No. : FG790812B