
Appendix C. Setup Photographs


<Radiated Emission>

X Plane for 22H

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : C1 of C3
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2


Report No.: FG790812A

Z Plane for24E

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJN7-TP00089ASI Page Number : C2 of C3
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report No. : FG790812A


Report Template No.: BU5-FG22/24/27 Version 1.2

Y Plane for 27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJN7-TP00089ASI Page Number : C3 of C3
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report No. : FG790812A

Report Template No.: BU5-FG22/24/27 Version 1.2