

## Appendix D. Setup Photographs

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D1 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report No.: FR6N0822-08E

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D2 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5




Report No. : FR6N0822-08E

## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D3 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5