

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJN7-TP00089ASI

: E1 of E3 Page Number Report Issued Date: Nov. 29, 2017

Report No.: FR790812E

Report Version : Rev. 01




Report No.: FR790812E

<Radiated Emission>

802.11a / n HT40 / ac VHT80 Tx Mode

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJN7-TP00089ASI Page Number : E2 of E3 Report Issued Date: Nov. 29, 2017 Report Version : Rev. 01






802.11n HT20 Tx Mode

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJN7-TP00089ASI Page Number : E3 of E3
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report No.: FR790812E