## Appendix C. Setup Photographs

## <Conducted Emission> Mode 1



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Report Issued Date: Jan. 04, 2017
Report Version: Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

: C1 of C3

Page Number

Report No.: FR6N0822-08A





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 34 INT TROOPS

FCC ID: 2AJN7-TP00086AUC


Page Number : C2 of C3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1


C Test Report No.: FR6N0822-08A

## <Radiated Emission>

LF



HЕ



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : C3 of C3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1