Appendix D. Setup Photographs

<Conducted Emission> Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D1 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report No.: FR6N0822-08C

Report Template No.: BU5-FR15CWL AC MA Version 1.3





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D2 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01


Report No.: FR6N0822-08C

Report Template No.: BU5-FR15CWL AC MA Version 1.3


CC Test Report No.: FR6N0822-08C

<Radiated Emission>

LF



HE



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D3 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 1.3