Appendix D. Setup Photographs

<Conducted Emission> Mode 1



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D1 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No. : FR6N0822-08B





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D2 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01


Report No. : FR6N0822-08B

Report Template No.: BU5-FR15CBT4.0 Version 1.3


CC Test Report No.: FR6N0822-08B

<Radiated Emission>

LF



HЕ



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086AUC Page Number : D3 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3