
3. Internal Photograph of EUT


Brand Name: Lenovo / Model Name: TP00086A

Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 13 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 14 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 15 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report No.: EP6N0822




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 16 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01



Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 17 of 32 Report Issued Date : Jan. 23, 2017 Report Version : Rev. 01




Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 18 of 32 Report Issued Date : Jan. 23, 2017 Report Version : Rev. 01

Report No.: EP6N0822




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 19 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01




Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 20 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 21 of 32 Report Issued Date : Jan. 23, 2017

Report Version : Rev. 01

Report No.: EP6N0822

Page Number


Report Version

: 22 of 32

: Rev. 01

Report Issued Date : Jan. 23, 2017

Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A



Brand Name: Lenovo / Model Name: TP00086A **WLAN Main Antenna for Sample 1**


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 23 of 32 Report Issued Date : Jan. 23, 2017 Report Version : Rev. 01

Report No.: EP6N0822




Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 24 of 32 Report Issued Date : Jan. 23, 2017 Report Version : Rev. 01

Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 25 of 32 Report Issued Date : Jan. 23, 2017



Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 26 of 32 Report Issued Date : Jan. 23, 2017




Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 27 of 32 Report Issued Date : Jan. 23, 2017

Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 28 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01



Brand Name: Lenovo / Model Name: TP00086A **WLAN Main Antenna for Sample 2**

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 29 of 32 Report Issued Date : Jan. 23, 2017

Report No.: EP6N0822



Report No.: EP6N0822




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 30 of 32 Report Issued Date : Jan. 23, 2017




Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A Page Number : 31 of 32
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01



Report No.: EP6N0822



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJN7-TP00086A IC: 21863-TP00086A

Page Number : 32 of 32 Report Issued Date : Jan. 23, 2017 Report Version : Rev. 01