

# Appendix D. Setup Photographs

# <Conducted Emission>

#### Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : D1 of D4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01


Report No.: FR790812C



## <Radiated Emission>

802.11b/g for Ant. 2/ 802.11n HT20 for Ant. 1+2

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : D2 of D4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01

Report No.: FR790812C

C Test Report No.: FR790812C

## 802.11b/g for Ant. 1

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : D3 of D4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01


CC Test Report No.: FR790812C

#### 802.11n HT40 for Ant. 1+2

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AJN7-TP00089ASI Page Number : D4 of D4
Report Issued Date : Nov. 29, 2017
Report Version : Rev. 01