
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 5

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : C1 of C3
Report Issued Date : Dec. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG8O2901-01B

X Plane for LTE Band 7

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : C2 of C3
Report Issued Date : Dec. 11, 2018
Report Version : Rev. 01


Report No.: FG8O2901-01B

Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG8O2901-01B

Y Plane for LTE Band 38

LF



HF



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : C3 of C3
Report Issued Date : Dec. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0