


Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1071 Page Number : 1 of 2
Report Issued Date : Feb. 14, 2018

Report No.: FR7N1101-03B


Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.2 Version 2.0




<Radiated Emission>

Y Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1071 Page Number : 2 of 2
Report Issued Date : Feb. 14, 2018
Report Version : Rev. 01

Report No.: FR7N1101-03B

Report Template No.: BU5-FR15CBT4.2 Version 2.0