
Test Setup Photographs


<Radiated Emission>

X Plane for Part22H

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 1 of 2
Report Issued Date : Jun. 01, 2017
Report Version : Rev. 01


Report No. : FG732005

Report Template No.: BU5-FG22/24 Version 1.2


Report No. : FG732005

Z Plane for Part24E

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 2 of 2
Report Issued Date : Jun. 01, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24 Version 1.2