

Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1093 Page Number : 1 of 2

Report Issued Date : Jun. 13, 2018
Report Version : Rev. 01

Report No.: FR832104-01C

Report Template No.: BU5-FR15CWL AC MA Version 2.0




Report No. : FR832104-01C


<Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1093 Page Number : 2 of 2
Report Issued Date : Jun. 13, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 2.0