
Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1178 Page Number : E1 of E2
Report Issued Date Jul. 25, 2019
Report Version : Rev. 01

Report No.: FR952704B


Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

<Radiated Emission> (Bluetooth v4.2/5.0 LE)





HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1178 Page Number : E2 of E2
Report Issued Date Jul. 25, 2019
Report Version : Rev. 01

Report No.: FR952704B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0