

Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 1 of 2
Report Issued Date : Jan. 25, 2018

Report No.: FR7O2602-02C

Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 2.0




<Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 2 of 2
Report Issued Date : Jan. 25, 2018

Report No.: FR7O2602-02C

Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0