

Appendix D. Setup Photographs


<Conducted Emission>

Mode 1

Front View



Side View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D1 of D2
Report Issued Date : Mar. 10, 2017
Report Version : Rev 01

Report Template No.: BU5-FR15CBT4.2 Version 2.0

Report No.: FR711304-01B



Report No. : FR711304-01B

<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D2 of D2
Report Issued Date : Mar. 10, 2017
Report Version : Rev 01

Report Template No.: BU5-FR15CBT4.2 Version 2.0