
Setup Photographs

<Conducted Emission>

Mode 5





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 1 of 3
Report Issued Date : Feb. 13, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7N1101-02







Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 2 of 3
Report Issued Date : Feb. 13, 2018
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7N1101-02


<Radiated Emission>

Mode 4

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 3 of 3
Report Issued Date : Feb. 13, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7N1101-02