
## Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : C1 of C3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No.: FG711304-01A


Report Template No.: BU5-FG22/24/27 Version 1.2

## X Plane for 24E

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : C2 of C3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No. : FG711304-01A


Report Template No.: BU5-FG22/24/27 Version 1.2

## Z Plane for 27L

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : C3 of C3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No. : FG711304-01A

Report Template No.: BU5-FG22/24/27 Version 1.2