


Appendix D. Setup Photographs

<Conducted Emission>

Front View



Side View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D1 of D2
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR711304-01C



<Radiated Emission>

X Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D2 of D2
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR711304-01C