

# Appendix A. Setup Photographs

### <Conducted Emission>

### Mode 1




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1032 Page Number : A1 of A3
Report Issued Date : Mar. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3



### Mode 5



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1032 Page Number : A2 of A3
Report Issued Date : Mar. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC711304


## <Radiated Emission>

### Mode 5

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1032 Page Number : A3 of A3
Report Issued Date : Mar. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3