## 3. Internal Photograph of EUT

Brand Name: Nokia; Model Name: TA-1037

Report No.: EP732005-03




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 12 of 32
Report Issued Date : Jun. 29, 2017





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 13 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 14 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 15 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 16 of 32 Report Issued Date : Jun. 29, 2017



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 17 of 32 Report Issued Date : Jun. 29, 2017




30 20 10 100 as 80 70

Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 18 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 19 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 20 of 32
Report Issued Date : Jun. 29, 2017






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 21 of 32
Report Issued Date : Jun. 29, 2017






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 22 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 23 of 32
Report Issued Date : Jun. 29, 2017






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 24 of 32 Report Issued Date : Jun. 29, 2017






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 25 of 32 Report Issued Date : Jun. 29, 2017




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 26 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 27 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 28 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01

Report No.: EP732005-03



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 29 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01


Report No.: EP732005-03



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037

Page Number : 30 of 32 Report Issued Date : Jun. 29, 2017

Report No.: EP732005-03



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 31 of 32
Report Issued Date : Jun. 29, 2017
Report Version : Rev. 01

Report No.: EP732005-03



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1037 Page Number : 32 of 32
Report Issued Date : Jun. 29, 2017