

Report No.: FR7O2602-02A

Setup Photographs

<Conducted Emission>






Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 1 of 2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 2 of 2
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No. : FR7O2602-02A