




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A29 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A30 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A31 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A32 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A33 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A34 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01

Conducted Spurious Emission




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A35 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A36 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A37 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A38 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A39 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01




TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A40 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A41 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A42 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A43 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01

Frequency Stability

Test Conditions		LTE Band 4 (QPSK) / Middle Channel	
Temperature (°C)		BW 10MHz	Note 2.
	Voltage (Volt)	Deviation (ppm)	Result
50	Normal Voltage	0.0003	
40	Normal Voltage	0.0013	
30	Normal Voltage	0.0045	
20(Ref.)	Normal Voltage	0.0000	
10	Normal Voltage	0.0033	
0	Normal Voltage	0.0030	
-10	Normal Voltage	0.0005	PASS
-20	Normal Voltage	0.0039	
-30	Normal Voltage	0.0047	
20	Maximum Voltage	0.0014	
20	Normal Voltage	0.0000	
20	Battery End Point	0.0001	

Note:

- 1. Normal Voltage =3.85 V.; Battery End Point (BEP) =3.435 V.; Maximum Voltage =4.4 V.
- 2. Note: The frequency fundamental emissions stay within the authorized frequency block.

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : A44 of A44
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01

Appendix B. Test Results of Radiated Test

Radiated Spurious Emission

LTE Band 4 / 5MHz / QPSK										
Channel	Frequency (MHz)	EIRP (dBm)	Limit (dBm)	Over Limit (dB)	S.G. Power (dBm)	TX Cable loss (dB)	TX Antenna Gain (dBi)	Polarization (H/V)		
Middle	3462	-42.34	-13	-29.34	-48.66	1.81	8.13	Н		
	5190	-34.43	-13	-21.43	-42.41	2.222	10.20	Н		
	6921	-53.75	-13	-40.75	-62.57	2.54	11.36	Н		
	3459	-45.04	-13	-32.04	-51.36	1.81	8.13	V		
	5190	-41.00	-13	-28.00	-48.98	2.222	10.20	V		
	6921	-53.09	-13	-40.09	-61.91	2.54	11.36	V		

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : B1 of B1
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01

Appendix D. Reference Report

Please refer to Sporton report number FG832104B which is issued separately.

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1136 Page Number : D1 of D1
Report Issued Date : Nov. 01, 2018
Report Version : Rev. 01