

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : D1 of D2
Report Issued Date Dec. 11, 2018
Report Version : Rev. 01


Report No.: FR8O2901-01B

Report Template No.: BU5-FR15CBT4.2 Version 2.0




<Radiated Emission>

X Plane LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : D2 of D2
Report Issued Date Dec. 11, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.2 Version 2.0

Report No.: FR8O2901-01B