

Appendix C. Setup Photographs

X plane for LTE Band 7

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1184 Page Number : C1 of C3
Report Issued Date : Apr. 16, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG930509-01B




Report No. : FG930509-01B

Y plane for LTE Band 2/4

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1184 Page Number : C2 of C3
Report Issued Date : Apr. 16, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No. : FG930509-01B

Z plane for LTE Band 5/12

LF



HF



——THE END——

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1184 Page Number : C3 of C3
Report Issued Date : Apr. 16, 2019
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0