# **Setup Photographs**

### <Conducted Emission>

#### Mode 3





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 1 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7O2602-02

Report No. : FC7O2602-02

Mode 4





Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 2 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


## <Radiated Emission>

#### Mode 4

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 3 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7O2602-02