FCC RF Test Report

APPLICANT : HMD Global Oy EQUIPMENT : Mobile Phone

BRAND NAME : Nokia MODEL NAME : TA-1181

FCC ID : 2AJOTTA-1181

STANDARD : FCC Part 15 Subpart C §15.247

CLASSIFICATION : (NII) Unlicensed National Information Infrastructure

We, Sporton International (Kunshan) Inc., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of Sporton International (Kunshan) Inc., the test report shall not be reproduced except in full.

Reviewed by: Jason Jia / Supervisor

JasonJia

Approved by: James Huang / Manager

Sporton International (Kunshan) Inc.

No. 1098, Pengxi North Road, Kunshan Economic Development Zone Jiangsu Province 215300 People's Republic of China

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1181 Page Number : 1 of 4
Report Issued Date : Jul. 29, 2019
Report Version : Rev. 01

Report No.: FR952704-03F

Report Template No.: BU5-FR15EWL B4AC MA Version 2.0

TABLE OF CONTENTS

Report No. : FR952704-03F

1	GEN	GENERAL DESCRIPTION		
	1.1	Applicant	. 4	
	1.2	Product Feature of Equipment Under Test	۷.	
	1.3	Product Specification of Equipment Under Test	. 4	
	1.4	Modification of EUT	. 4	

APPENDIX A. REFERENCE REPORT

 Sporton International (Kunshan) Inc.
 Page Number
 : 2 of 4

 TEL: 86-512-57900158
 Report Issued Date
 : Jul. 29, 2019

 FAX: 86-512-57900958
 Report Version
 : Rev. 01

FCC ID : 2AJOTTA-1181 Report Template No.: BU5-FR15EWL B4AC MA Version 2.0

REVISION HISTORY

Report No. : FR952704-03F

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FR952704-03F	Rev. 01	Initial issue of report	Jul. 29, 2019

 Sporton International (Kunshan) Inc.
 Page Number
 : 3 of 4

 TEL: 86-512-57900158
 Report Issued Date
 : Jul. 29, 2019

 FAX: 86-512-57900958
 Report Version
 : Rev. 01

FCC ID : 2AJOTTA-1181 Report Template No.: BU5-FR15EWL B4AC MA Version 2.0

1 General Description

1.1 Applicant

HMD Global Oy

Bertel Jungin aukio 9,02600 ESPOO. FINLAND

1.2 Product Feature of Equipment Under Test

Product Feature					
Equipment	Mobile Phone				
Brand Name	Nokia				
Model Name	TA-1181				
FCC ID	2AJOTTA-1181				
EUT supports Radios application	GSM/GPRS/EGPRS/WCDMA/HSPA/ DC-HSDPA/HSPA+(16QAM uplink is not supported) LTE/FM Receiver/GNSS/NFC WLAN 2.4GHz 802.11b/g/n HT20 WLAN 5GHz 802.11a/n HT20/HT40 WLAN 5GHz 802.11ac VHT20/VHT40/VHT80 Bluetooth BR/EDR/LE				
HW Version	LLDM690A				
SW Version	LLDB701				
EUT Stage	Identical Prototype				

Report No.: FR952704-03F

Remark:

- **1.** The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.
- 2. This is a change FCC ID report, the difference between previous and current is dual SIM card change to single SIM card, the change has no influence on the test results, all the test results are leveraged from original report FR952704-01F.

1.3 Product Specification of Equipment Under Test

Standards-related Product Specification					
Tx/Rx Channel Frequency Range	5745 MHz ~ 5825 MHz				
Type of Modulation	802.11a/n: OFDM (BPSK / QPSK / 16QAM / 64QAM) 802.11ac: OFDM (BPSK / QPSK / 16QAM / 64QAM / 256QAM)				
Antenna Type / Gain	IFA Antenna with gain -1.00 dBi				

1.4 Modification of EUT

No modifications are made to the EUT during all test items.

 Sporton International (Kunshan) Inc.
 Page Number
 : 4 of 4

 TEL: 86-512-57900158
 Report Issued Date
 : Jul. 29, 2019

 FAX: 86-512-57900958
 Report Version
 : Rev. 01

FCC ID: 2AJOTTA-1181 Report Template No.: BU5-FR15EWL B4AC MA Version 2.0

Appendix A. Reference Report

Please refer to Sporton report number FR952704-01F which is issued separately.

Report No. : FR952704-03F

 Sporton International (Kunshan) Inc.
 Page Number
 : A1 of A1

 TEL: 86-512-57900158
 Report Issued Date
 : Jul. 29, 2019

 FAX: 86-512-57900958
 Report Version
 : Rev. 01

FCC ID : 2AJOTTA-1181 Report Template No.: BU5-FR15EWL B4AC MA Version 2.0