
## **Test Setup Photographs**


## <Radiated Emission>

X Plane for Part 22H/27L

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 1 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 1.2


Report No. : FG7O2602-02A

## Y Plane for Part 24E For GSM1900

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 2 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 1.2

Report No.: FG7O2602-02A




## Z Plane for Part 24E For WCDMA1900

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1056 Page Number : 3 of 3
Report Issued Date : Jan. 25, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2