Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1179 Page Number : E1 of E2
Report Issued Date Apr. 30, 2019
Report Version : Rev. 01


Report No.: FR930509-04B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0


<Radiated Emission> (Bluetooth v4.0 LE)

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1179 Page Number : E2 of E2
Report Issued Date Apr. 30, 2019
Report Version : Rev. 01

Report No.: FR930509-04B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0