

Report No.: FR711304-01E

Appendix D. Setup Photographs

<Conducted Emission>

Mode 2

Front View



Side View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D1 of D2 Report Issued Date: Mar. 10, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.4




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : D2 of D2
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No.: FR711304-01E

Report Template No.: BU5-FR15EWL Version 1.4