
Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1093 Page Number : 1 of 3
Report Issued Date : Jun. 13, 2018
Report Version : Rev. 01

Report No.: FR832104-01A


Report Template No.: BU5-FG22/24/27 Version 2.0

Z Plane for 24E

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1093 Page Number : 2 of 3
Report Issued Date : Jun. 13, 2018
Report Version : Rev. 01


Report Template No.: BU5-FG22/24/27 Version 2.0

Report No.: FR832104-01A


Report No. : FR832104-01A

Z Plane for 27L

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1093 Page Number : 3 of 3
Report Issued Date : Jun. 13, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0