


Report No.: FR711304-01A

Appendix B. Setup Photographs


<Conducted Emission>

Mode 1

Front View



Side View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : B1 of B2
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0




Report No.: FR711304-01A


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJOTTA-1038 Page Number : B2 of B2
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0