
Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2/5/7/12/38

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1084 Page Number : 1 of 3
Report Issued Date : Jun. 12, 2018
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG832104B

X Plane for LTE Band 13

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1084 Page Number : 2 of 3
Report Issued Date : Jun. 12, 2018


Report No.: FG832104B

Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 2.0

Z Plane for LTE Band 66

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1084 Page Number : 3 of 3
Report Issued Date : Jun. 12, 2018

Report No.: FG832104B

Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0