


# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : A1 of A3
Report Issued Date : Mar. 10 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3

Report No. :FC711304-01



#### Mode 5





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : A2 of A3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3




# <Radiated Emission>

## Mode 5

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AJOTTA-1038 Page Number : A3 of A3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3