


Report No.: FR7N1101-02C

## **Setup Photographs**

## <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 1 of 3
Report Issued Date : Feb. 13, 2018

Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0



## Report No.: FR7N1101-02C


## <Radiated Emission>

X Plane for 802.11b

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 2 of 3
Report Issued Date : Feb. 13, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0




Y Plane for 802.11g/n

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1048 Page Number : 3 of 3
Report Issued Date : Feb. 13, 2018
Report Version : Rev. 01

Report No.: FR7N1101-02C

Report Template No.: BU5-FR15CWL Version 2.0