

Setup Photographs

<Conducted Emission>

Mode 5





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1071

Page Number : 1 of 3 Report Issued Date : Feb. 14, 2018 Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7N1101-03

Mode 4





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1071 Page Number : 2 of 3
Report Issued Date : Feb. 14, 2018

Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7N1101-03


<Radiated Emission>

Mode 4

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AJOTTA-1071

Page Number : 3 of 3 Report Issued Date : Feb. 14, 2018 Report Version : Rev. 01

Report No. : FC7N1101-03

Report Template No.: BU5-FC15B Version 1.3