

Appendix D. Setup Photographs

<Conducted Emission>





TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : D1 of D2
Report Issued Date Dec. 11, 2018
Report Version : Rev. 01

Report No.: FR8O2901-01A


Report Template No.: BU5-FR15CBT Version 2.0




Report No. : FR8O2901-01A

<Radiated Emission>

X Plane LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AJOTTA-1092 Page Number : D2 of D2
Report Issued Date Dec. 11, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0