

FCC ID: 2AJT8-HB100

Page 1 of 4

## **External Photos**

**EUT Name:** Localizer **EUT Model:** HB100

**FCC ID:** 2AJT8-HB100

FCC Title 47, Part 15, Subpart C, ANSI C63.10:2013

## Prepared for:

Nancy Confrey Health Beacons Inc.

PO Box 753, 34 Walden St. Concord MA 01742 USA

Tel: (987) 287-4635 Fax: (978) 246-6019

## Prepared by:

TUV Rheinland of North America

762 Park Avenue

Youngsville, NC 27596 Tel: (919) 554-3668 Fax: (919) 554-3542 http://www.tuv.com/

Report/Issue Date: 30 November 2016

Report Number: Supplement to 31652438.001 - External Photos

Report Number: Supplement to 31652438.001 - External Photos

EUT: Localizer Model: HB100

## **External Photos:**



Figure 1 – External Photos of EUT with internal loop antenna and external probe antenna



Figure 2 – External Photos of EUT with battery compartment exposed.



Figure 3 – Rear view of EUT

Page 4 of 4