


Report No.: FR742534-01A

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308 Page Number : 1 of 3
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308 Page Number : 2 of 3
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0






<Radiated Emission>
Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308 Page Number : 3 of 3
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01

Report No.: FR742534-01A

Report Template No.: BU5-FR15CBT Version 2.0