


Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308 Page Number : 1 of 3
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01

Report No.: FR742534-01C

Report Template No.: BU5-FR15CWL MA Version 1.3





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308 Page Number : 2 of 3
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL MA Version 1.3




Report No.: FR742534-01C

<Radiated Emission> Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AJZB-0308

Page Number : 3 of 3 Report Issued Date : Aug. 01, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3