

August 30, 2017

FCC ID: 2AJZLNW1000

Dear Sir or Madam,

We hereby attest that the NIGHTWATCH® device's UWB transmitter is disabled while the device is charging. The device is equipped with a power management IC that can identify the presence of a charge source. Following the detection of a charge source, the NIGHTWATCH® device firmware disables the UWB transmitter.

Sincerely,

Jeffrey R. Schab Founder & CEO

