Rentokil Initial

Rentokil Initial 1927 plc Riverbank Meadows Business Park Camberley Surrey GU17 9AB T: +44 (0) 1276 607444

CLASS II PERMISSIVE CHANGE REQUEST

7th June 2018

Element Materials Technology 100 Frobisher Business Park Leigh Sinton Road Malvern, Worcestershire WR14 1BX UK

RE: Class II Permissive Change Request

FCC ID: 2AK3PGSD-500349

To Whom It May Concern:

Please be advised that pursuant to FCC Rule 47CFR 2.1043 the manufacturer requests that the above-referenced model be approved for class II permissive change.

The reason for the class II change is adding a new host Bed Bug Monitor GSD-801014 to the Limited Module Approval covering the above LoRa module at a power level 0x06.

Thank you for your attention to this matter.

Yours faithfully

Rentokil Initial 1927 plc

Ning Pan